



Please read before start-up!

Operating instructions

Universal drilling and milling machines

Version of 09/2009

F1200 – F1200 hs with high speed motor
CC-F1200 – CC-F1200 hs with high speed motor

F1210 – F1210 hs with high speed motor
CC-F1210 – CC-F1210 hs with high speed motor

F1410 LF – F1410 LF hs with high speed motor
CC-F1410 LF – CC-F1410 LF hs with high speed motor

Walter Blombach GmbH
Tool and Machine Factory

D-42899 Remscheid Am Blaffertsberg 13
D-54673 Neuerburg WABECO Str. 1-10

phone: (02191) 597-0 fax: (02191) 597-40
phone: (06564) 9697-0 fax: (06564) 9697-25
www.wabeco-remscheid.de

E-Mail: info@wabeco-remscheid.de
E-Mail: neuerburg@wabeco-remscheid.de

Dear customer!

Congratulations on choosing the **WABECO Universal Drilling and Milling Machine**. We have taken great care in its manufacture and we have given it a thorough quality control test. These operating instructions are to help you to work with it safely and properly. Therefore we request that you read the respective instructions carefully and follow them exactly.

After unpacking the machine please check to see if any kind of damage has occurred during transportation. Any complaints must be made immediately. Complaints made at a later date **cannot** be accepted.

Duplications or copies of this document of any kind, or of excerpts, require a written approval by WABECO

Disposal of the drilling and milling machine

The transport and protective packaging is made by means of the following materials:

- corrugated cardboard
- polystyrene free of freon
- polyethelene foil
- non-returnable wooded pallet (untreated)
- Euro pallet (deposit)

If you have no further need of these articles or do not wish to use them again, please dispose of them at the public recycling facilities.

The drilling and milling machine consists up to 98% of recyclable materials, i.e. steel, cast iron, aluminium and 2% of chemical materials, e.g. the coating of electrical leads, printed circuits.

If you have trouble in disposing of these parts in a proper manner, we would be pleased to help you: upon mutual agreement we will take the complete machine back and dispose of it.

However, the costs for transporting the machine to our plant must be at your expense.

Index

EC-Conformity Declaration	5
1. Dimensions	6
1.1 F1200 – F1210	6
1.2 F1200 – F1210 high speed	7
1.3 F1410 with trapezoid thread spindle	8
1.4 F1410 with ball screw	9
1.5 F1410 high speed with ball screw	10
2. Delivery and installation	11
3. Transport lock	12
4. Start-up and maintenance	13



Index

5.	Safety devices and recommendations	16
6.	Clamping and ejecting tools	18
7.	Assembly and disassembly of collets	20
8.	Speed regulation	21
8.1	Speed regulation for machining aluminium and steel	21
8.2	Speed regulation for 1.4 kW motor	21
8.3	Speed regulation for 2.0 kW motor (high speed)	22
9.	Feed motion X,Y und Z-axis	23
10.	Recommendations for application and operation	24
10.1	Swivelling of the milling head	25
10.2	Drill stroke – depth stop	26
11.	Coolant unit	27
12.	Declaration of noise levels	28
13.	Drawing and list of parts	29
	<u>F1200 – F1200 high speed - F1210 – F1210 high speed</u>	
13.1	Elektronis – protective cover with 1.4 kW motor	29
13.3	Protective cover	31
13.4	Milling head with 1.4 kW motor	32
13.5	Milling head high speed with 2.0 kW motor	34
13.7	Z-column with vertical slide and trapezoid thread	38
13.8	Z- column with vertical slide and ball screw	40
13.11	Z- column with vertical slide with automatic feed	46
13.18	Z-spindle complete	60
13.19	Lateral drive for Z-spindle complete	61
13.21	Lateral drive for Z-spindle complete with automatic feed	64
13.22	Cross support with trapezoid thread spindle	66
13.23	Cross support with ball screw	68
13.30	X-spindle	77
13.31	Y-spindle	78
13.34	X-spindle with automatic feed	84
13.35	Y-Spindel spindle with automatic feed	86
	<u>CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed</u>	
13.2	Elektronis – protective cover with 1.4 kW motor	30
13.3	Protective cover	31
13.4	Milling head with 1.4 kW motor	32
13.6	Milling head high speed with 2.0 kW motor	36
13.9	Z-column with vertical slide and trapezoid thread	42
13.10	Z- column with vertical slide and ball screw	44
13.19	Lateral drive for Z-spindle complete	61
13.20	Z-spindle with CNC-drive complete	62
13.24	Cross support with trapezoid thread spindle	70
13.32	X-spindle	80
13.33	Y-spindle	82

Index

<u>CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed</u>		
13.36	Control console nccad with 1.4 kW motor	88
13.37	Control console nccad with 2.0 kW motor	90
13.38	Support arm for control console	92
<u>F1410 LF– F1410 high speed</u>		
13.1	Elektronis – protective cover with 1.4 kW motor	29
13.3	Protective cover	31
13.4	Milling head with 1.4 kW motor	32
13.5	Milling head high speed with 2.0 kW motor	34
13.12	Z-column with trapezoid thread spindle	48
13.13	Vertical slide with trapezoid thread spindle	50
13.14	Z-column with ball screw	52
13.15	Vertical slide with ball screw	54
13.18	Z-spindle complete	60
13.19	Lateral drive for Z-spindle complete	61
13.25	Top slide	72
13.26	Cross slide with trapezoid thread spindle	73
13.27	Cross slide with ball screw	74
13.30	X-spindle	77
13.31	Y-spindle	78
13.34	X-spindel with automatic feed	84
13.35	Y-spindel with automatic feed	86
<u>CC-F1410 LF– CC-F1410 high speed</u>		
13.2	Elektronis – protective cover with 1.4 kW motor	30
13.3	Protective cover	31
13.4	Milling head with 1.4 kW motor	32
13.6	Milling head high speed with 2.0 kW motor	36
13.16	Z- column with ball screw	56
13.17	Vertical slide with ball screw	58
13.19	Lateral drive for Z-spindle complete	61
13.20	Z-spindle complete	62
13.28	Top slide	75
13.29	Cross slide	76
13.32	X-spindle	80
13.33	Y-spindle	82
13.36	Control console nccad with 1.4 kW motor	88
13.37	Control console nccad with 2.0 kW motor	90
13.38	Support arm for control console	92
14.	Circuit diagram	93
14.1	Motor 1.4 kW	93
14.2	Motor high speed 2.0 kW	94
14.3	nccad with 1.4 kW motor	95
14.4	nccad with 2,0 kW motor	96
14.5	Stepper motor basic version	97
14.6	Stepper profi version	98

EC – Conformity Declaration

Version 07.2010

In the name of the manufacturer

Walter Blombach GmbH

**Tool and Machine Factory
based in Remscheid and Neuerburg**

D-42871 Remscheid Postfach 12 01 61 Phone: 0049 (2191) 597-0 Fax: 0049 (2191) 597-40
D-54673 Neuerburg WABECO Str. 1-10 Phone: 0049 (6564) 9697-0 Fax: 0049 (6564) 9697-25

We hereby declare that the universal milling and drilling machines specified below

Universal milling and drilling machine Typ:
F1200 - F1200 hs with high speed motor
CC-F1200 - CC-F1200 hs with high speed motor
F1210 - F1210 hs with high speed motor
CC-F1210 - CC-F1210 hs with high speed motor
F1410 LF - F1410 LF hs with high speed motor
CC-F1410 LF - CC-F1410 LF hs with high speed motor

meet the following regulation requirements for standard series production

- **directive for machines 2006/42 EG**
- **EMV directive 89/336/EWG**

In order to meet / implement the requirements of the above mentioned directives, the following applicable and previously published standards have been adhered to:

EN ISO 12100-1
EN ISO 12100-2
EN 13128
EN 60204-1

D-54673 Neuerburg

City



Christoph Schneider

Technical Director





1. Dimensions

1.1 F1200, F 1210 with trapezoid thread spindle or ball screw





1. Dimensions

1.2 F1200, F 1210 high speed with trapezoid thread spindle or ball screw




1. Dimensions

1.3 F1410 with trapezoid thread spindle




1. Dimensions

1.4 F1410 with ball screw



1. Dimensions

1.5 F1410 high speed with ball screw



2. Delivery and installation

The drilling and milling machines are carefully packed in our factory.

Please check the following upon receipt of delivery:



1. **Whether the packaging has been damaged and/or:**
2. **Whether the drilling and milling machine shows signs of transport damage or if there are reasons for complaints. In this case we request your immediate notification. Claims made at a later date cannot be considered.**

The drilling and milling machine must be installed on an appropriate, level and firm base.

This would be, for example:

- a base cabinet such as in our accessories' programme
- an own work bench as long as it is strong enough to carry the weight of the machine without warping (see technical data and check with spirit level) and has an even surface
- a steel plate


The drilling and milling machine must be firmly screwed down onto the base. To facilitate this, there are 10 mm holes in the machine base. **Good results and a minimum of vibration during operation can only be guaranteed if the above mentioned requirements for secure mounting have been adhered to.**

The installation of the machine should take place where there is sufficient lighting, electrical cables with earthed sockets and 0-conductors are installed adequately near to the machine so that the mains connection lead is not subject to any tension whatsoever. The mains lead should be such that, by means of a multiple socket, a coolant or lubrication unit can also be connected.

3. Transport lock

F1410 high speed with ball screw

Transport lock



Attention!

The transport lock must be removed prior to the initial start-up of the machine.

Please proceed as follows:

1. Remove the wooden block below the milling spindle by slightly moving the milling head upward via the handwheel of the z axis.
2. Remove the snap ring on both sides of the transport lock. Now the lock can be moved easily. Otherwise, the milling head has to be moved until the wire ropes are tensioned and carry the weight. Now the transport lock can be pulled out.

4. Start-up and maintenance

After the machine has been professionally installed and securely mounted, it must be connected to the mains supply.


1. A qualified electrician must connect the supply lead of the drilling and milling machine to the local power supply.
2. Provide sufficient lubrication coolant for running the coolant unit (optional).
3. All functions must be checked.

In order to clamp workpieces a machine vice or clamping screws (suitable for the T grooves) may be used.

Greasing the milling machine

Every 6-8 weeks the **Quill** and the **feed pinion** should be greased (see sketch).

Therefore move the quill up and down while applying some lubricant to the lateral metal-on-metal contact area of the quill and the feed spindle.



It is not necessary to lubricate the **drilling spindle**, as the ball bearings are fully enclosed and had been lubricated during production for the entire service life of the machine.

The **milling machines with linear guides** are maintenance-free and do not need greasing.

Lubrication means:

- reducing the wear and the frictional resistance
- extending the lifetime
- preventing the metal surfaces from corroding

We recommend:

for lubrication:	multi-purpose grease grade 2NLGI
for oiling:	lubrication oil of 100 mm ² /s viscosity

Spindle nuts with trapezoid thread spindle:

The spindle nuts of the milling machines are adjustable.

Should a spindle nut of one of the three axes have some play, proceed as follows:



4. Start-up and maintenance

X-axis:

To adjust the spindle nut, move the cross table to the centre. After loosening the set screw, the adjusting nut is to be turned a bit in the clockwise direction. Turning the adjusting nut like this achieves a mutual tightening of the two nuts and as a result play-free running of the threaded spindle. After the adjustment, the set screw must be re-tightened firmly.

Y-axis:

The readjustment of the Y-axis requires unscrewing the concertina cover of the top slide. The following procedure is as per instruction for the X-axis.




4. Start-up and maintenance

Z-axis:

To adjust the spindle nut of the Z-axis, you have to unscrew the cover plate.

The further procedure is as for the X-axis.



In the case of spindle nuts with ball screw an adjustment is not necessary and also not possible.

5. Safety devices and recommendations

In order to make working with our drilling and milling machines safe, we have equipped them with the following safety devices and thus they are in accordance with the relevant European safety regulations.

1. **Protective cover**

The separating safety device attached to the machine housing, prevents reaching in and coming into contact with the tool spindle. This safety device is constructed in such a way that it can be adjusted to the necessary working height (depending on the dimensions of the workpiece and tool).

2. **Main switch with low voltage release**

In order to disconnect the electrical parts of the drilling and milling machine safely from the mains, we have provided a main switch with low voltage release besides the mains lead with plug. This undervoltage release prevents the drive motor from coming on after a power cut and so excludes the danger of the work spindle moving unexpectedly.

3. **Emergency OFF switch**

This enables a quick interruption of dangerous movements, in particular of the CNC equipment.

4. **Overload protection**

This device has been developed to protect the drive motor and it must be noted that after the motor has been turned off (by hand or automatically), because of overloading, a short pause of 1-3 seconds must be observed before turning the machine on again so that the relay of the electrical parts can re-establish the closed circuit condition.

5. **Safety machine cabin**

During the CNC operation the door of the safety machine cabin must be closed. On the right upper side there is a limit switch that is operated by closing the door. This is the only way to move the feed motors at the axes independently via the controller.

Only with the door closed it is possible that the feed motors at the axes are moved independently via the CNC-controller. When the door is open, the motors are being switched off the power supply which enables manual operation. The main spindle can be switched on either when the door is closed or opened.

Working in manual mode with the door opened.

When switching from manual operation to CNC mode please proceed as follows:

1. close the door of the safety machine cabin
2. turn the flip switch from manual operation to CNC operation
3. select main spindle rotating direction left or right
4. set the spindle speed by means of the potentiometer
5. release the flip switch to move the axes
6. start the CNC programme

It is forbidden to remove the door limit switch or to put it out of action as this could lead to serious danger to the machine operator and cause severe accidents.

5. Safety devices and recommendations

We would like to draw your attention to the following safety recommendations which are a result of a combination of the European standards and our own experience:




1. Workpieces must be secured in such a way that they cannot be propelled out of position by the torque of the drill or mill.
2. Round workpieces such as corrugated pieces, round turning part or similar things must be fixed into position by suitable means such as prisms in conjunction with a machine vice when drilling.
3. Machine drills and mills are sharp-edged tools. In order to protect hands, these tools should only be held by the shaft and **not** by the cutting edge when being transported or changed.

The cutting edges of the tools are sharp and can cause serious injury when touched.

4. Throughout the drilling and milling processes, sharp and often hot swarf is produced which is then thrown off by the momentum of the tool in operation. In order to prevent accidents it is necessary to wear goggles or a face shield.
5. It is furthermore recommended to wear well-fitting clothes, especially on the arms (nothing loose) and in the case of long hair, a hair net should be worn to prevent anything being caught or drawn in by the rotating work spindle or when changing the workpieces.
6. By pulling the mains plug, the drilling and milling machine is disconnected from the electrical current. This should be observed when
 - a drill or mill is changed
 - the machine has to be serviced.
7. In order to avoid wear and tear on the tools and the drive motor, it is recommended that the tools are to be selected with care, worn tools should be exchanged for sharp ones and the feed should be calculated such that the r.p.m. of the work spindle is only slightly reduced. The depth of the feed must be selected with precision so that it is not possible to drill into the support table.
8. We recommend the installation of light which provides a level of at least 500 lux at the point of tool cutting operations.
9. Appropriate means must be used to dispose of drilling and milling swarf.
10. We strongly recommend that the drill chuck key is be fixed to the machine by means of a clamp or similar attachments only. This is in order to avoid the drill chuck key being caught by the tool spindle and being thrown around if it is fixed to the machine with anything flexible like chains or string.
11. When drilling and milling machines are not in use, we recommend installing a safety device to prevent children or non authorized people from switching on the machine.
12. The drilling and milling machine should be set up where no humidity, apart from the lubrication coolant, can affect it.
13. It is necessary to carry out regular checks for damages to parts and/or for the functions, on drilling and milling machines. Please do not hesitate to call us if you require original spare parts or advice!

6. Clamping and ejecting tools



6. **Clamping and ejecting tools**



This is the core of the WABECO clamping and ejection system, **the tool retaining/forcing screw**. It operates on the principle of the screw having a fine thread located at its head and a coarse thread on the shank. Due to this construction, a special procedure has to be observed when clamping tools with an internal thread.

It is not possible to insert a tool or tool holder with internal threads into the work spindle first and to screw the tool retaining/forcing screw into the internal thread afterwards! The tool or tool holder must be screwed onto the tool retaining/forcing screw.

As you can see on the picture (page 18), for clarification we have cut open the protective cover and the spindle housing so that the tool retaining screw with the Allen key can be seen.

Please proceed as follows:

With the aid of the Allen key, screw the tool retaining/forcing screw into the work spindle right up to the end of its thread. Once the screw blocks, turn it back 2-3 revolutions.

Now the tool is inserted by hand from underneath into the taper of the work spindle and screwed onto the tool retaining/forcing screw. While this is being done, the tool retaining screw is held tight by means of the Allen key.

Once the tool has been clamped hand-tight, the work spindle is held by means of the holding pin and the tool retaining screw can be tightened with the Allen key without any effort.

To eject **tools with an internal thread**, hold the tool spindle tight with the holding pin and loosen the tool retaining screw with the Allen key.

Now the tool can be screwed off the tool retaining/forcing screw by hand and taken out of the work spindle taper from underneath.

Tools with flat tang (without internal threads) can be clamped by first of all screwing the tool retaining screw as far back with the Allen key as is necessary to insert the tool into the work spindle. After doing this, the tool retaining/forcing screw is screwed lightly onto the tool.


To eject the tool, the holding pin is inserted into the tool spindle and held tight with one hand. By turning the Allen key to the left, the tool is released and can be easily removed from the work spindle.

7. Assembly and disassembly of collets

Disassembly

Take the clamping nut in one hand and press it against the collet as you can see it on the illustration.


The lateral pressure exerted on the collet causes the clamping nut to leap so that can easily be taken out of the nut.



Assembly

Put the collet on a flat underlay and place the clamping nut on the collet.

Now press the clamping nut down against the collet until it snaps. The collet can move freely in the central chamfer. It will not fall out even if you turn it around.



8. Speed regulation

A specific cutting speed is required when milling different materials (e.g. steel, aluminium etc.)
 The r.p.m. of the work spindle can be infinitely varied from 140-3000 min⁻¹ or 100–7500 min⁻¹ on the potentiometer respectively, so that the appropriate speed for the material, the workpiece and the diameter of the cutter can be chosen every time.

Please see the table showing the respective r.p.m. values for aluminium and steel as follows:

8.1 Speed regulation for machining aluminium and steel

ALUMINIUM		STEEL	
tool-Ø	r.p.m. ⁻¹	tool-Ø	r.p.m. ⁻¹
2 mm	3000	2 mm	2000
4 mm	2900	4 mm	1400
6 mm	2850	6 mm	1200
8 mm	2750	8 mm	850
10 mm	2700	10 mm	700
12 mm	2650	12 mm	590
14 mm	2600	14 mm	500

8.2 Speed regulation for 1.4 kW motor

%	r.p.m. ⁻¹
1	140
5	140
10	150
15	160
20	200
25	300
30	400
35	700
40	850
45	1000
50	1200
55	1500
60	1900
65	2500
70	2800
80	3000
90	3000
100	3000

8. Speed regulation

8.3

Speed regulation for **2.0 kW motor** (high speed)


%	r.p.m. ⁻¹
2	50
3	100
4	200
5	350
10	700
15	1000
20	1400
25	1700
30	2100
35	2500
40	2900
45	3200
50	3600
55	4050
60	4500
65	4800
70	5200
75	5600
80	6050
85	6500
90	6900
95	7200
100	7500

9. Feed motion X,Y and Z-axis

The traverse and longitudinal motion of the cross support (X,Y-axis) is accomplished by turning the handwheels (parts-no. 4 and 12). Both slides can be blocked by means of the clamping levers (parts-no. 21 and 3).

The feed motion – drilling and milling depth (Z-axis) – is accomplished by using the handwheel (part-no. 20). To operate the milling head by means of the handwheel, loosen clamp lever (part-no. 18) and fix it again after operation.

The travel path can be read from the scale rings. One graduation mark corresponds to 0.05 mm. A complete revolution of the handwheel corresponds to a slide path at the X-axis (scale ring part no. 15) and Y-axis (scale ring part no. 5) of 4 mm, with ball screws 5 mm, at the Z-axis (scale ring part no. 33) of 2 mm. with ball screws of 2.5 mm.



Another possibility of operating the tool spindle is by turning the operating lever (part no. 29). After loosening the clamping lever (part-no. 39) the control lever can be turned. One graduation mark on the collar (part-no. 31) corresponds to 1 mm of travel.

The clamping lever must be well tightened again afterwards. The work spindle has a maximum travel of 55 mm.

We recommend that the feed range (infeed) should not be selected too generously, but that in the case of greater infeed depth this should be accomplished in multiple steps.

10. Recommendations for application and operation

We recommend the following:

- the drill should be inserted and clamped with the chuck key in such a way that the drill is positioned exactly between the three clamping jaws of the toothed ring chuck, the quick action chuck or the drawing-in attachment of the drill
- mills with a shaft should be clamped by means of a precision draw-in attachment with morse taper MT2 and tightening thread M10 and the appropriate precision clamping collet in accordance with DIN (German Industrial Standard)
- mills with a bore hole (all those with a \varnothing of 16 mm) and a longitudinal groove should be clamped by means of precision shell end mill with mill retaining screw and feather key, MT2x16, draw-in tightening thread M10

It is important to observe the following when drilling:

- the appropriate r.p.m. must be set according to the diameter of the drill
- the contact pressure should be such that the drill can still cut with ease
- when the contact pressure is too high it will result in premature wear on the drills, even the possible snapping of drills or them sticking fast in the bore hole

If a drill sticks fast, switch the motor off immediately, use the emergency OFF switch.

- when processing hard materials, i.e. steel, normal commercial drilling oil must be used
- the spindle must always rotate when the drill is removed from the workpiece
- when processing non-metallic materials, i.e. wood and when having to drill right through, splintering can be prevented by clamping a piece of waste wood under the material to be processed
- when processing veneered or plastic-coated workpieces of wood, always drill from the good side
- when processing thin metal sheeting, a piece of waste wood should always be clamped underneath

It is important to observe the following when milling:

- choose the appropriate cutting speed:
for materials with normal mechanical strength properties, e.g. steel 18-22m/min
for materials with higher mechanical strength properties 10-14m/min
(see also paragraph 9 - r.p.m. adjustment)
- regulate the contact pressure so that the cutting speed remains constant
- when processing hard materials use normal commercial drilling oil

It is important to observe the following when clamping the workpieces:

- use suitable straining screws or machine vices for the T-slots of the milling machine table
- always remove waste material and swarf from the milling machine table of the cross support in order to clamp level and accurately

10. Recommendations for application and operation

10.1 Swivelling of the milling head

In order to produce bore holes and chamfering at an angle which diverges from the normal vertical position of the milling head, the milling head can be swivelled up to 90° either to the right or to the left.

If an adjustment is intended please proceed as follows:


After loosening (turn to the left) the lock nut (part-no. 7) turn the hexagon nut as far to the right against the housing of the tool spindle until the index pin (part-no. 4) can be pulled out by hand.

Loosen both the high nut (part-no. 19) and the hexagon nut (part-no. 21) on the vertical slide by then turning to the left.

Now the milling head can be swivelled to the desired degree to the left or to the right. In order to fix the milling head in this position, tighten both the high nut and the hexagon nut again.

In order to bring the milling head back to its normal position, loosen the high nut and the hexagon nut on the vertical slide and bring the vertical slide back to its upright position.

After turning back the hexagon nut on the index pin, the latter can be pushed into the opening in the work spindle housing by hand. Now, both the hexagon nut and the lock nut of the index pin as well as the hexagon nut and the high nut on the vertical slide can all be tightened.




10. Recommendations for application and operation

10.2 Drill stroke – depth stop

It is also possible to set the feed motion of the milling spindle to a specified measure.

Therefore, the desired depth can be adjusted by means of the operating lever (part no. 27,28,29) (depth can be read from the scale ring part no. 31), and the depth stop part no. 37 is to be turned to the correct position, so that it hits the milling head. Then tighten the hexagon bolt (part no. 36).



11. Coolant unit

The coolant unit consists of:

1. Tray with lubrication coolant pump which collects the lubrication coolant mixture from the feed pump.
Content: Coolant unit 13 litres
 Safety machine cabin 42 litres
2. Feed pump with the following electrical data:
 - nominal voltage 230 V
 - frequency 50/60 Hz
 - nominal current input 0,4A
 - nominal output 0,07 kW
 - ON-OFF switch and mains lead with a length of 2 m complete with earthed plug
3. Adjustable, flexible pressure tubing with stop valve and nozzle: for transporting the lubrication coolant to the processing point.

When using lubrication coolants, especially water based emulsions, a number of health and safety measures must be observed:

1. use concentrated products free of nitrates
2. use concentrates without secondary amines
3. use products with the lowest possible allergy potential

When mixing a refill of lubrication coolant, please observe the following:

- clean/rinse the circulation system (tray/filter)
- determine the concentration necessary to meet the technical demands (concentrate: water 1:5 – 1:30)
- check the water has a low level of nitrates (< 50 mg NO₃⁻, test strip)

A cleaning plan should determine at what intervals the system should be cleaned of swarf and other waste.

A service plan should determine the following:

- when to check the concentration in use (daily/weekly)
- when to check the pH values (weekly)
- when to check/assess the bacteria count (monthly)
- when to check the nitrate content (weekly)

(The information in brackets can be varied according to the production circumstances)

In order to reduce splashing, we recommend the attachment of a splash guard and/or reducing amount sprayed from the nozzle.

Since steps to protect the skin must be taken, it is advisable to wear gloves and aprons. The skin should be cleaned with acidic syndets without abrasive ingredients and rich cream should be applied to regenerate the skin.

Please also adhere to the enclosed information on the general operating instructions.

12. Declaration of noise levels in accordance with DIN EN 24871 (German Industrial Standard)

Noise levels while running idle

Acoustic capacity level	78 dB (A)
Sound pressure level on operator's ear	62 dB (A)

The stated values reflect emission levels and not necessarily working levels. Although there is a correlation between the level of emission and the level of stress, this cannot be used reliably in order to determine whether additional safety measures are necessary or not.

Other factors which influence the actual stress level of employees are the characteristics of the working area, other sources of noise, i.e. the number of machines and other processes going on nearby etc. Apart from that, the permitted stress levels may vary from country to country.

This information enables the user of the machine to assess the dangers and risks more accurately. However, in order to state a reference value of noise levels which could manifest itself to the ears of the operator during processing, the following measurement conditions are given:

Shell end mill 10 mm, cutting depth 3 mm


Spindle r.p.m. 2240 1/min, feed 0,09 mm/revolution, AlCuMgPb-cuboid workpiece

The adjusted sound pressure level is 91 dB (A).

13. Drawing and list of parts

13.1 Electronics – protective cover for milling machines with **with 1.4 kW motor** F1200 – F1210 - F1410 LF


Part-No.	Pieces	Order-No.	Designation
1	1	11200401	Cap
2	1	11800005	Circuit board
3	1	11200403	Cover
4	4	11700001	Countersunk screw
5	4	11700002	Hexagon nut
5.1	4	11700120	Locking washer
6	1	11800001	ON/OFF switch
7	1	11800004	Potentiometer
8	8	11700003	Tapping screw
9	2	11200405	board rest
11	1	11200411	Tool draw-in bolt with thread M10 for MT2
11	1	112004111	Tool draw-in bolt with thread M12 for MT3/SK30
12	1	11800008	Emergency OFF switch (german)
15	1	11200415	Allen key 8 mm for MT2
15	1	112004151	Allen key 10 mm for MT3/SK30



13. Drawing and list of parts

13.2 Electronics – protective cover for CNC milling machines **with 1.4 kW motor** CC-F1200 – CC-F1210 – CC-F1410 LF

Part-No.	Pieces	Order-No.	Designation
1	1	11200401	Cap
2	1	11800005	Circuit board
3	1	112004031	Cover
4	4	11700001	Countersunk screw
5	4	11700002	Hexagon nut
5.1	4	11700120	Locking washer
8	8	11700003	Tapping screw
9	2	11200405	Board rest
11	1	11200411	Tool draw-in bolt with thread M10 for MT2
11	1	112004111	Tool draw-in bolt with thread M12 for MT3/SK30
15	1	11200415	Allen key 8 mm for MT2
15	1	112004151	Allen key 10 mm for MT3/SK30



13. Drawing and list of parts


13.3 Protective cover for all milling machines

F1200 - F1200 high speed - CC-F1200 - CC-F1200 high speed

F1210 - F1210 high speed - CC-F1210 - CC-F1210 high speed


F1410 LF - F1410 LF high speed - CC-F1410 LF - CC-F1410 LF high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11270101	Protective cover
2	1	11270102	Clamping fixture
2.1	1	11840004	Clamping lever
3	1	11270103	Guide rod
3.1	3	11700026	Screws
3.2	2	11700038	Washer
7	1	51007250-0001	Brass die



13. Drawing and list of parts

13.4 Milling head for milling machines with **1.4 kW motor** F1200 – F1210 - F1410 LF – CC-F1200 – CC-F1210 - CC-F1410 LF




13. Drawing and list of parts

13.4 Milling head for milling machines **with 1.4 kW motor** F1200 – F1210 - F1410 LF – CC-F1200 – CC-F1210 - CC-F1410 LF

Part-No.	Pieces	Order-No.	Designation
1	1	11200101	Housing
2	1	11200102	Plastic ring
3	2	11810001	Ball bearing
4	1	11700005	Circlip
5	1	11820001	Drive belt
6	1	11200106	Belt pulley
7	1	11700006	Feather key
8	1	11200108	Bearing flange
9	1	11700046	Hexagon socket srew
10	2	11830001	Limpet washer
11	1	11700027	Circlip
12	1	11700011	Screw
13	3	11700123	Hexagon socket screws
14	1	11200114	Tool spindle MT2
14	1	112001141	Tool spindle MT3
14	1	112001142	Tool spindle SK30
15	1	11200115	Feather wire
16	2	11810002	Ball bearing
17	1	11200117	Quill
19	1	11200119	Nut thin
20	1	11200120	Nut thick
21	1	11200121	Feather key
22	1	11200122	Pinion shaft
23	1	11700018	Washer
24	2	11700010	Hexagon socket srew
25	2	11200125	Spacer sleeve
26	1	11200126	Motor with pinion Z12
27	1	11200127	(Wheel) hub
28	1	11200128	Activating lever
29	1	11840001	Handle
30	1	11700016	Spiral clamp pin
31	1	11200131	Scale ring
32	1	11700004	Cylinder head screw
33	1	11700012	Circlip
34	1	11700121	Hexagon socket screw
36	1	11700092	Hexagon srew
37	1	11200137	Depth stop
38	1	11850001	Spiral spring
39	1	11840002	Clamping lever

13. Drawing and list of parts

13.5 Milling head for milling machines high speed **with 2.0 kW motor** F1200 high speed – F1210 high speed - F1410 LF high speed




13. Drawing and list of parts

13.5 Milling head for milling machines high speed **with 2.0 kW motor** F1200 high speed – F1210 high speed - F1410 LF high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11202101	Housing
2	1	11200102	Plastic ring
3	1	11700116	Hexagon socket screw
4	1	11700005	Circlip
5	1	11820002	Drive belt <i>F1200 high speed - F1210 high speed</i>
	1	11820010	Drive belt <i>F1410LF high speed</i>
6	1	11202106	Belt pulley
7	1	11700006	Feather key
8	1	11200108	Bearing flange
9	2	11810001	Ball bearing
10	6	11700060	Limpet washer
11	1	11700025	Circlip
12	1	11700046	Hexagon socket screw
13	3	11700123	Hexagon socket screws
14	1	11200114	Tool spindle MT2
14.1	1	112001141	Tool spindle MT3
14.2	1	112001142	Tool spindle SK30
15	1	11200115	Spring wire
16	2	11810021	Spiral bearing
17	1	11200117	Quill
18	2	11810022	Nilos ring (special seal washer)
19	1	11200119	Nut thin
20	1	11200120	Nut thick
21	1	11200121	Feather key
22	1	11200122	Pinion shaft
23	1	11700018	Washer
24	2	11700123	Hexagon socket screw
25	1	11202125	Flange
26	1	11239	Motor high speed
27	1	11200127	(Wheel) hub
28	1	11200128	Activating lever
29	1	11840001	Handle
30	1	11700016	Spiral pin
31	1	11200131	Scale ring
32	1	11700124	Cylinder head screw
33	1	11700012	Circlip
34	1	11700121	Hexagon socket screw
35	1	11800029	Operating cover
36	1	11700092	Hexagon screw
37	1	11200137	Depth stop
38	1	11850001	Spiral spring
39	1	11840002	Clamping lever
41	2	11700036	Hexagon socket screw
42	1	11700051	Flat-headed screw
43	1	11202143	Thrust washer
44	1	11202144	Motor belt pulley
45	2	11700021	Hexagon socket screw
48	1	11200416	Allen key 8 mm MT2
48.1	1	112004161	Allen key 10 mm MT3/SK30
49	1	11200411	Tool draw-in bolt with thread M10 MT2
49.1	1	112004111	Tool draw-in bolt with thread M12 MT3/SK30
50	1	11800008	Emergency OFF switch
51	1	11202151	Protective cover

13. Drawing and list of parts

13.6 Milling head for CNC milling machines high speed **with 2.0 kW motor** CC-F1200 high speed – CC-F1210 high speed - CC-F1410 LF high speed




13. Drawing and list of parts

13.6 Milling head for CNC milling machines high speed **with 2.0 kW Motor** CC-F1200 high speed – CC-F1210 high speed - CC-F1410 LF high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11202101	Housing
2	1	11200102	Plastic ring
3	1	11700116	Hexagon socket screw
4	1	11700005	Circlip
5	1	11820002	Drive belt <i>F1200 high speed - F1210 high speed</i>
	1	11820010	Drive belt <i>F1410 LF high speed</i>
6	1	11202106	Belt pulley
7	1	11700006	Feather key
8	1	11200108	Bearing flange
9	2	11810001	Ball bearing
10	6	11700060	Limpet washer
11	1	11700025	Circlip
12	1	11700046	Hexagon socket screw
13	3	11700123	Hexagon socket screws
14	1	11200114	Tool spindle MT2
14.1	1	112001141	Tool spindle MT3
14.2	1	112001142	Tool spindle SK30
15	1	11200115	Spring wire
16	2	11810021	Spiral bearing
17	1	11200117	Quill
18	2	11810022	Nilos ring (special seal washer)
19	1	11200119	Nut thin
20	1	11200120	Nut thick
21	1	11200121	Feather key
22	1	11200122	Pinion shaft
23	1	11700018	Washer
24	2	11700123	Hexagon socket screw
25	1	11202125	Flange
26	1	11239	Motor high speed
27	1	11200127	(Wheel) hub
28	1	11200128	Activating lever
29	1	11840001	Handle
30	1	11700016	Spiral pin
31	1	11200131	Scale ring
32	1	11700124	Cylinder head screw
33	1	11700012	Circlip
34	1	11700121	Hexagon socket screw
36	1	11700092	Hexagon screw
37	1	11200137	Depth stop
38	1	11850001	Spiral spring
39	1	11840002	Clamping lever
41	2	11700036	Hexagon socket screw
42	1	11700051	Flat-headed screw
43	1	11202143	Thrust washer
44	1	11202144	Motor belt pulley
45	2	11700021	Hexagon socket screw
48	1	11200416	Allen key 8 mm MT2
48.1	1	112004161	Allen key 10 mm MT3/SK30
49	1	11200411	Tool draw-in bolt with thread M10 MT2
49.1	1	112004111	Tool draw-in bolt with thread M12 MT3/SK30
51	1	11202151	Protective cover

13. Drawing and list of parts

13.7 Z-column with vertical slide for milling machines with **trapezoid thread spindle**
F1200 – F1200 high speed – F1210 – F1210 high speed




13. Drawing and list of parts

13.7 Z-column with vertical slide for milling machines with **trapezoid thread spindle** F1200 – F1200 high speed – F1210 – F1210 high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11200301	Column
2	1	11200302	Adjusting strip
3	1	11200303	Vertical slide
4	1	11700017	Index bolt
5	1	11700018	Washer
6	1	11700019	Hexagon nut
7	1	11700020	Lock nut
8	1	11700021	Hexagon socket screw
9	3	11700123	Threaded pin
10	1	11840004	Clamping lever
11	4	11200311	Thrust piece
12	3	11700019	Hexagon nut
13	1	11860001	Concertina cover
14	1	11700022	Screw
15	1	11200315	Concertina cover guide
17	4	11700124	Threaded pin
18	1	11200329	Washer
19	1	11700125	Screw
20	1	11700028	Stud bolt
21	1	11700030	Hexagon nut
22	1	11700029	Washer
23	1	112003261	Counter nut
24	1	11200326	Nut
25	1	11700009	Headless pin
26	2	11700038	Washer
27	1	11200320	Cover plate
28	12	11700026	Screw
29	1	11870001	Alu scale

13. Drawing and list of parts

13.8 Z-column with vertical slide for milling machines with **ball screw** F1200 – F1200 high speed – F1210 – F1210 high speed




13. Drawing and list of parts

13.8 Z-column with vertical slide for milling machines with **ball screw** F1200 – F1200 high speed – F1210 – F1210 high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11200301	Column
2	1	11200302	Adjusting strip
3	1	11200303	Vertical slide
4	1	11700017	Index bolt
5	1	11700018	Washer
6	1	11700019	Hexagon nut
7	1	11700020	Lock nut
8	2	11700021	Hexagon socket screw
9	3	11700123	Headless pin
10	1	11840004	Clamping lever
11	4	11200311	Thrust piece
12	3	11700019	Hexagon nut
13	1	11860001	Concertina cover
14	1	11700022	Screw
15	1	11200315	Concertina cover guide
17	4	11700124	Headless pin
18	1	11200329	Washer
19	1	11700125	Screw
20	1	11700028	Stud bolt
21	1	11700030	Hexagon nut
22	1	11700029	Washer
23	1	11245326	Nut holder
24	1		Spindle nut (contained in ball screw order no.11245327)
25	4	11700039	Screw
26	2	11700038	Washer
27	1	11200320	Cover plate
28	12	11700026	Screw
29	1	11870001	Alu scale

13. Drawing and list of parts

13.9 Z-column with vertical slide for CNC milling machines **trapezoid thread spindle** CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed




13. Drawing and list of parts

13.9 Z-column with vertical slide for CNC milling machines **trapezoid thread spindle** CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11200301	Column
2	1	11200302	Adjusting strip
3	1	11200303	Vertical slide
4	1	11700017	Index bolt
5	1	11700018	Washer
6	1	11700019	Hexagon nut
7	1	11700020	Lock nut
8	1	11700021	Hexagon socket screw
9	3	11700123	Headless pin
10	1	11840004	Clamping lever
11	4	11200311	Thrust piece
12	3	11700019	Hexagon nut
13	1	11860001	Concertina cover
14	1	11700022	Screw
15	1	11200315	Concertina cover guide
17	4	11700124	Headless pin
18	1	11200329	Washer
19	1	11700125	Screw
20	1	11700028	Stud bolt
21	1	11700030	Hexagon nut
22	1	11700029	Washer
23	1	112003261	Counter nut
24	1	11200326	Nut
25	1	11700009	Headless pin
26	2	11700038	Limpet washer
27	1	11200320	Cover plate
28	12	11700026	Screw
29	1	11870001	Alu scale

13. Drawing and list of parts

13.10 Z-column with vertical slide for CNC milling machines **with ball screw** CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed




13. Drawing and list of parts

13.10 Z-column with vertical slide for CNC milling machines **with ball screw** CC-F1200 – CC-F1200 high speed – CC-F1210 – CC-F1210 high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11200301	Column
2	1	11200302	Adjusting strip
3	1	11200303	Vertical slide
4	1	11700017	Index bolt
5	1	11700018	Washer
6	1	11700019	Hexagon nut
7	1	11700020	Lock nut
8	2	11700021	Hexagon socket screw
9	3	11700123	Headless pin
10	1	11840004	Clamping lever
11	4	11200311	Thrust piece
12	3	11700019	Hexagon nut
13	1	11860001	Concertina cover
14	1	11700022	Screw
15	1	11200315	Concertina cover guide
17	4	11700124	Headless pin
18	1	11200329	Washer
19	1	11700125	Screw
20	1	11700028	Stud bolt
21	1	11700030	Hexagon nut
22	1	11700029	Limpet washer
23	1	11245326	Nut holder
24	1		Spindle nut (contained in ball screw order no.11245327)
25	4	11700039	Screw
26	2	11700038	Limpet washer
27	1	11200320	Cover plate
28	12	11700026	Screw
29	1	11870001	Alu scale

13. Drawing and list of parts

13.11 Z-column with vertical slide for Milling machines **with automatic feed** F1200 – F1200 high speed – F1210 – F1210 high speed




13. Drawing and list of parts

13.11 Z-column with vertical slide for Milling machines **with automatic feed** F1200 – F1200 high speed – F1210 – F1210 high speed

Part-No.	Pieces	Order-No.	Designation
1	1	11200301	Column
2	1	11200302	Adjusting strip
3	1	11200303	Vertical slide
4	1	11700017	Index bolt
5	1	11700018	Limpet washer
6	1	11700019	Hexagon nut
7	1	11700020	Lock nut
8	1	11700021	Hexagon socket screw
9	3	11700123	Threaded pin
10	1	11840004	Clamping lever
11	4	11200311	Thrust piece
12	3	11700019	Hexagon nut
13	1	11860001	Concertina cover
14	1	11700022	Screw
15	1	11200315	Concertina cover guide
17	4	11700124	Threaded pin
18	1	11200329	Washer
19	1	11700125	Screw
20	1	11700028	Stud bolt
21	1	11700030	Hexagon nut
22	1	11700029	Washer
23	1	112003261	Counter nut
24	1	11200326	Nut
25	1	11700009	Threaded pin
26	2	11700038	Limpet washer
27	1	11200320	Cover plate
28	12	11700026	Screw
29	1	11870001	Alu scale

13. Drawing and list of parts

13.12 Z-column for milling machines with linear guides with trapezoid thread spindle F1410 LF



13. Drawing and list of parts

13.12 Z-Column for milling machines with linear guides **with trapezoid thread spindle** F1410 LF

Part-No.	Pieces	Order-No.	Designation
1	1	16400301	Z-Column
2	1	16400203	Base plate
3	1	11200320	Cover plate
4	4	11700033	Screw
5	4	11700034	Spring lock washer
6	2	11700035	Hexagon nut
7	2	11810023	Guide rail 460 mm
8	29	11700031	Screw
9	2	11810024	Guide rail 580 mm
10	1	16400224	Spindle extension
11	4	11700046	Screw
12	1	16400342	bush
13	2	11700125	Screw
14	2	11700031	Screw
15	4	11700019	Nut
17	10	11700026	Screw